



Republic of the Philippines  
Department of the Interior and Local Government  
**PHILIPPINE PUBLIC SAFETY COLLEGE**  
MWSS Compound, Katipunan Road cor. Ayala Heights,  
Old Balara, Quezon City



---


**NFTI-Canlubang**

**LIST OF KEY PERSONNEL**


**[Rehabilitation of Perimeter Fence Around OSA Compound]**

- a. **Project Manager (Licensed Civil Engineer) with at least Five (5) years of experience as Project Manager**
- b. **Project Engineer (Licensed Civil Engineer) with at least five (5) years of experience as Project Engineer**
- c. **Project Material Engineer (Licensed Civil Engineer), DPWH accredited with at least five (5) years of experience as Project Material Engineer**
- d. **Project Safety Officer, DOLE accredited with at least one (1) year of experience as Safety Officer**
- e. **General Foreman with at least five (5) years of experience**
- f. **Backhoe Operator, must have Training Certificate accredited by DOLE and/or TESDA**

Prepared by:

  
**NICOMEDES A. PASCUAL**  
Technical Inspector

Submitted by:

  
**ENGR. ROMY V. YALO**  
Acting Chief, GSS, AD